

Sl. No.	Tests	Minimum Quantity Required	Test Charges (Rs.) per Sample
*	COLOUR MEASUREMENT [SPECTROPHOTOMETER]		
321)	Colour Measurement (L, a, b values) or Reflectance/Whiteness	0.5 m	350
322)	Colour Measurement (L, a, b values) of Powder		600
323)	Colour Difference (K/S, Delta E) Sample vs. Standard	0.5 m	500
324)	Chromaticity diagram after measurement (marine light)		1000
325)	Absorbance of dilute solution of water soluble dyes per dye	50 g	500
326)	Whiteness index of powder sample	50 g	600
327)	Active content of OBA/FBA on cellulose (water soluble) using UV visible absorbance spectrophotometer	50 g	500
328)	Active content of OBA/FBA on synthetics (solvent soluble) using UV visible absorbance spectrophotometer	50 g	1000
329)	Gloss Test	0.5 m	400